



**ITT Industries**

**ITT McDonnell & Miller**

3500 N. Spaulding Ave.

Chicago, IL 60618

tel: 773 267-1600

fax: 773 267-6591


www.mcdonnellmiller.com



October, 2003

## Product Bulletin Improvement to Manual Reset Mechanism On 150S/157S Level Controls

McDonnell & Miller is pleased to announce an improvement to the manual reset versions of the Series 150S/157S products with products manufactured beginning in October 2003 (date code 03K). The change involves replacing the existing button type microswitch with a mechanical latching mechanism. This is a more robust design which will address the occasional problems you have seen with hard to reset controls. The diagrams below show the location of the reset mechanism and change to the bracket mechanism.



Due to this change, the availability of repair and replacement parts has been affected.

- Replacement switch assemblies (SWA-150S-M and SWA-158S-M) for units manufactured prior to October 2003 (03K) will no longer be offered. A replacement head would need to be purchased which will upgrade the unit to the new design.
- Units manufactured October 2003 (03K) and beyond will use the SWA-150S replacement switch assembly if replacement of switches is necessary.

The installation instructions for 150S products (MM-217, MM-219) and replacement switch assemblies (MM-235) have been updated to reflect this change. The parts catalog (MM-701) will be updated at the next printing. In the meantime, the version of the parts catalog in the M&M website has been updated.

Contact the local McDonnell & Miller Manufacturer's Representative or McDonnell & Miller Technical Service if you have any questions.

